Utah Department of Environmental Quality Division of Drinking Water

Public Water System Inventory Report

Run Date: 08/04/2011 12:58 pm

PWS ID: UTAH26011 Name: SNAKE CREEK MUTUAL WATER

Legal Contact SNAKE CREEK MUTUAL WATER Rating: Approved

DAVE GOBLE Rating Date: 12/30/1899

Address: PO BOX 446 Activity Status: Active

MIDWAY, UT 84049

Phone Number: 435-714-0679

City Served (Area):

County: WASATCH COUNTY

Gal/Day Gal/Min

System Type: Non-community

Last Inv Update: 04/29/2010

Activity Status Cd: Active

Last Snty Srv Dt: 08/31/2009

Total Dsgn Cap:

Surveyor: DWIGHT HILL

Total Emerg Cap:

Oper Period: 1/1 to 12/31

Contacts

Contact			Phone		
Type	Name	Title	Office	Emergency	Email Address
AC	GOBLE, DAVE	435-	-654-5848	435-714-0678	mollyglobe@earthlink.net

Service Connections

Connection Type	Meter Type Code	Meter Size	Number Connections	
Residential	Unknown	0	54	
			54 T c	tal Svc Connections

Storage

Total Storage: 117,000 GAL Number of Units: 1 Adequate Capacity: NO

No.	Name	Type	Effective Volume	Constr Matri	Overflow Elev	Activity Status	Press'd
ST001	MORGAN-SPENCER RESERVOIR	Ground	117,000 GAL	Concrete		Α	NO

Treatment Plants

No.	Plant Name	Approved Design Capacity (gal/day)	Activity Status	Process
TP003	SPRING CHLORINATOR		Α	

Distribution System

Pump Type	Total Dyn Head	Pressure	Cross	Auhority
	ft H2O P.S.I.	Adequate	Connection	Statement
		No		

Sources

No.	Source Name	Activity Status	Source Type	Well Dia.	Safe Yield *	Pump Capacity	Location Data On File	Water Type	Availability	Period of Operation	Grnd Wtr Indicator
WS001	WEST SPRING	Inactive	SP				Yes	GW	Other		_
WS002	EAST SPRING	Inactive	SP				Yes	GW	Other		
WS003	LOWER MILL FLAT SPRING	Active	SP				Yes	GW	Permanent	1/1 to 12/31	

^{*}Reports measured flow for wells, approved design capacity for all other sources.